Car Repair

Technician report: 4913737



•

You can see above that you can create and use custom headers. You can also create and use footers in the same way.

Basic Information		
Technician Name	John Doe	
Date of Check	29/01/2021	



Following the "Report Car" heading, sections are created with the repeatable sections. Additionally conditional rules were set to show the detailed checklist only if an issue was reported. Rules for conditional color were also set to highlight the table cells color in green if there is no issue and red if there is.

Report Car	
License Plate	BD5I SMR
Fluids - Check list	Ok
Tires - Check list	Issue
Tire Checklist Detail	 ☑ Tires pressure ☐ Change tire front left ☐ Change tire front right ☐ Change tire back left ☐ Change tire back right ☐ Rotate tires
Lights - Check list	Issue
Lights Checklist Detail	□ Front headlight left □ Front headlight right ☑ Rear headlight left ☑ Rear headlight right □ Left turn signal □ Right turn signal
Additional Maintenance Required Description	Tire pressure seems to be off in the left front and left rear tires. Neither of the rear headlights work.
Comments & Images	no files

Report Car		
License Plate	DF8W LPW	
Fluids - Check list	Issue	

Car Repair

Technician report: 4913737



Fluids Checklist Detail	☑ Oil refill ☐ Oil change ☐ Coolant refill
Tires - Check list	Ok
Lights - Check list	Ok
Additional Maintenance Required Description	Refill oil. Found spark plug below the car, all spark plugs inside the car are present.
Comments & Images	

Report Car	
License Plate	78TR 2W2
Fluids - Check list	Ok
Tires - Check list	Ok
Lights - Check list	Ok
Additional Maintenance Required Description	Hand on speedometer stuck at the end of the clock.
Comments & Images	240 260 280 300

Finish	
Final comments	All checks were performed, all issues were reported.