

i

This default PDF was generated via NestForms. You can <u>clone this example form</u> <u>into your account</u>, start collecting and exporting data into this template in seconds.

Report details for the Event - A1234X Johnson Smith

A1234X Johnson Smith - Ben Thompson

15/01/2025

General Survey Details

Question	Answer
Project serial number	A1234X
Project name	Field boundary enlargement 1234
Name of property owner	Don Smith
Date of survey	15/01/2025
Property address line 1	Green Meadow Farm Willow Lane Fernbrook, Somerset
Postcode	TA12 4XY
GPS Location	53°43'4"N 6°21'23"W

Boundary Markers

Question	Answer
Are all property corner markers present and visible	Yes



Question	Answer
Corner marker issues	
Comments	Comments: All good - no issues
Condition of Boundary Markers	Intact
Description of Boundary Marker Type	Wooden stake

Property Lines and Features

Question	Answer
Are property lines free of encroachments?	Νο
Encroachment issues	
Comments	Comments: Nearby extensive building works - potential to cause problems - to be checked
Identify any structures near property lines	Wind turbine, Fences, Buildings



Question	Answer
<i>Nearby structure issues</i>	
Comments	Comments: Should not cause any issues with the area - note major building works (being checked)
Distance Measurements Between Key Points (m) - North to South markers	250
Distance Measurements Between Key Points (m) - East to West markers	100
Describe any natural features affecting boundaries	South side affected by conservation issues and pasture
Affecting boundary issues	
Comments	Comments: Protected and agricultural land - no application plans for major works
Any further comments	Comments: Some concerns about nearby reservoir - to be addressed - 28/02/2025



Question	Answer
Images	

Surveyor and Client Sign-off

Question	Answer
Surveyor first name	Alan
Surveyor Last name	Johnson
Signature	ASS - SA
Client first name	Don
Client Last name	Smith
Signature	Coluit
Date of inspection	15/01/2025