

•

This default PDF was generated via NestForms. You can <u>clone this example form</u> <u>into your account</u>, start collecting and exporting data into this template in seconds.

## Report details for the Event - Rob Rob \_

**Rob Rob** \_ - Admin Template

15/02/2024

## **Inspecting Person and Location**

Question	Answer
First Name	Rob
Last Name	Cairns
Location/Premises	Smiths Shopping Centre
Address line 1	M# Retail Park
Address line 2	Blanchtown
City/Town	Bluetown
County	Dublin
Postcode/Eircode	A## H## T
GPS Location	53°18'43"N 5°25'6"W
Type of inspection?	Air Conditioner

## **Air Conditioner**

Question	Answer
Electrical Current	Ok
Condenser coil	Action required



Question	Answer
Condenser coil action required	Comments: All units to be replaced as per last audits/inspections
Blower speed	Ok
Blower belt assembly	Action required
Belt assembly action required	Comments: All new units to be inspected by quality control. Use quality control checklist app
Blower belt condition	Good condition
Amp draw/compressor	Action required
Amp draw/compressor action required	Comments: All units to have secondary checks completed by the end of the year
Compressor contactor	Good



Question	Answer
Compressor contact action required	Comments: No issues
Air filter	Action required
Air filter action required	Comments: All units to be replaced. New units passed by quality control and ready to be installed
Cut-out switch and setting	Ok
Check thermostat	Correct
Thermostat action	Comments: Correct and no issues
Condensate drain line	Good
Evaporator coil	Good



Question	Answer
Evaporator coil action required	Comments: No issues
Refrigerant level	Good
Refrigerant level action required	WENCES  WENCES
Correct operating pressure	Yes

## Sign off





Question	Answer
Please sign	
Date & Time	15/02/2024
Re-inspection date	17/04/2024 16:41