

This default PDF was generated via NestForms. You can <u>clone this example form</u> <u>into your account</u>, start collecting and exporting data into this template in seconds.

Report details for the Event - Whiteley Park, Gwent, GW67 2346B

Whiteley Park, Gwent, GW67 2346B - Admin Template

11/12/2023

Question	Answer
Address/Area/Street name	Whiteley Park, Gwent, GW67
GPS Location	53°58'34"N 6°22'47"W
Date & Time of Inspection	11/12/2023
What is the general condition of the poles in the area?	Require attention
<i>How many poles are visible in the area</i>	7

Inspection Details

Damaged poles

Question	Answer
Are there any broken or damaged components on the poles?	Yes
Is the pole leaning or warped?	Yes

1 / 4 Report generated by <u>www.nestforms.com</u> 19/04/2024 17:29



Question	Answer
<i>Image - pole leaning or warped</i>	Comments: Pole 3 and 4. Accident inspection required
Are there any signs of corrosion or rust?	Yes
Image - Corrosion/Rust	Comments: Bolt condition. Full inspection required.
Are there any loose wires or cables at the base of the pole?	No
Are there any hazardous materials present?	No
Are there any signs of animal or bird nests on the poles?	Yes
Wild-life - images	Comments: Request Nature survey be undertaken. Contact RSPB



Question	Answer
Are there any signs of vegetation growing on the pole?	Yes
Images - Vegetation	Comments: Site clearance required
Are there any nearby power lines or other infrastructure near the pole?	Yes
Power lines and infrastucture comments and images	Comments: Contact the local grid for advice. Complete Health and Safety risk Assessment
Are there any potential safety hazards around the pole?	No
<i>Comments & Images - Potential Safety Hazards</i>	Comments: Massed cables nearby. Contact grid for advice. Health and Safety audit required.



Question	Answer
Any other potential risks associated with the pole?	Νο

Inspection Sign Off

Question	Answer
First name	Alan
Last name	Smith
Staff Number	2346B
Please sign	KCANAXA
Date & Time	11/12/2023